



### **State Water Resources Control Board**

January 11, 2016

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7015 1520 0001 8019 5661

Battalion Chief Andrew Wordin Office of the Fire Marshal Fire Prevention Bureau 200 North Main Street, 17th Floor Los Angeles, CA 90012 andrew.wordin@lacity.org

SUBJECT:

FAILURE TO COMPLY; UNDERGROUND STORAGE TANK SYSTEMS LOCATED AT LOS ANGELES CITY FIRE STATION # 49, 400 EAST YACHT STREET, WILMINGTON

### Dear Chief Wordin:

As of the date of this letter, the State Water Resources Control Board (State Water Board) has not received a response to our November 5, 2015 Notice of Violation (NOV)(attached). You are directed to correct the ongoing violations identified in the NOV and submit compliance documentation to the State Water Board and the Los Angeles City Fire Department within ten (10) days from the date of this letter.

Please send all compliance documentation to the following:

# **State Water Board**

Ms. Rebecca Green
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
1001 I Street, 16<sup>th</sup> Floor
Sacramento, California 95814
rebecca.green@waterboards.ca.gov

## **Local CUPA**

Mr. Aaron Mungaray
Fire Inspector
Los Angeles City Fire Department
200 Main Street, Suite 1700
Los Angeles, California 90012
aaron.mungaray@lacity.org

Failure to comply with this notice may result in an enforcement action by the State Water Board. The State Water Board reserves the right to bring an action against the owner and/or operator of the tank(s) in violation, or it may recommend that the Los Angeles City Fire Department pursue enforcement, or the Los Angeles City Fire Department may elect to pursue enforcement independently.

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at Amantha. Henkel@waterboards.ca.gov.

Sincerely,

Amantha Henkel Senior Environmental Scientist UST Enforcement Unit

Attachment: November 5, 2015 Notice of Violation

cc: (via email only)

Office of Enforcement

Ms. Anna Olekszyk
Acting CUPA Manager
Los Angeles City Fire Department
anna.olekszyk@lacity.org

Battalion Chief Curt Klafta Los Angeles City Fire Department curt.klafta@lacity.org

Captain Dan Dragotto
Los Angeles City Fire Department
daniel.dragotto@lacity.org

Mr. Aaron Mungaray Fire Inspector Los Angeles City Fire Department aaron.mungaray@lacity.org

Mr. Steve Hillman General Services Department City of Los Angeles steve.hillman@lacity.org

Mr. Sean Sullivan
General Services Department
City of Los Angeles
sean.sullivan@lacity.org

Mr. Joshua Muncie General Services Department City of Los Angeles joshua.muncie@lacity.org







#### State Water Resources Control Board

November 5, 2015

(Via email and Certified Mail) **CERTIFIED MAIL** NO. 7015 0640 0006 0950 4339

Chief Curt Klafta Underground Storage Tank Unit Los Angeles City Fire Department 200 North Main Street, Suite 1700 Los Angeles, California 90012 curt.klafta@lacity.org

SUBJECT:

NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS

LOCATED AT LOS ANGELES CITY FIRE STATION # 49, 400 EAST YACHT

STREET, WILMINGTON

### Dear Chief Klafta:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on October 22, 2015, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and title 23, California Code of Regulations (CCR), chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Operating Permit – The facility permit to operate is expired.	All	October 22, 2015	Ongoing	H&SC 25284(a)
2	Failure to Maintain Facility and Tank Information (A&B Forms) – Tank form B in CERS has not been approved by the CUPA and was not onsite at the time of inspection. The form contains errors and needs to be updated to include: drop tube shut-off valve, strike plate if applicable, method of corrosion protection, and verify the installation date.	All	October 22, 2015	Ongoing	H&SC 25286(a); 23 CCR 2711(a)
3	Failure to Maintain Monitoring Plan – The monitoring plan was not onsite at the time of inspection. The document in CERS has not been approved by the CUPA. The plan contains errors and needs to be updated to include: automatic tank gauging, and edit the recordkeeping section for accuracy.	All	October 22, 2015	Ongoing	H&SC 25286(a); 23 CCR 2711(a)(9)

No.	Violation	Tank	Start Date	Stop Date	Regulation
4	Failure to Submit or Update Plot Plan/Site Map – The site plan in CERS is incomplete and has not been approved by the CUPA. It does not identify monitoring equipment or a scaled diagram which indicates the location of the UST systems with respect to buildings or other landmarks.	All	October 22, 2015	Ongoing	H&SC 25286(a); 23 CCR 2711(a)(8)
5	Failure to Maintain Response Plan Onsite – The response plan was not onsite at the time of inspection. The document in CERS has not been approved by the CUPA.	All	October 22, 2015	Ongoing	23 CCR 2712(i)
6	Failure to Notify Local Agency of DO – The owner statement of designated UST operator form in CERS is not signed.	All	October 22, 2015	Ongoing	23 CCR 2715(a)
7	Failure to Monitor Product Piping – The sensor in the unleaded sump is unable to detect a leak at the earliest opportunity because it is on the wrong side of the sump. The sensor in the diesel sump is unable to detect a leak because the test boots are on and the sensor is not at the lowest point in the sump. Sensors must be located at the lowest point in the sump, directly beneath product piping.	All	October 22, 2015	Ongoing	23 CCR 2630(d)
8	Failure to Tag Monitoring Equipment – The line leak detectors did not have annual monitoring certification tags.	All	October 22, 2015	Ongoing	23 CCR 2638(f), 2641(j)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and the Los Angeles City Fire Department within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

## State Water Board

Ms. Rebecca Green
UST Enforcement Unit
State Water Resources Control Board
1001 I Street, 16<sup>th</sup> Floor
Sacramento, California 95814
rebecca.green@waterboards.ca.gov

# **Local CUPA**

Mr. Aaron Mungaray
Fire Inspector I
Los Angeles City Fire Department
200 Main Street, Suite 1700
Los Angeles, California 90012
aaron.mungaray@lacity.org

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,

Amantha Henkel Senior Environmental Scientist UST Enforcement Unit

Office of Enforcement

cc: (via email only)

Ms. Anna Olekszyk
Acting CUPA Manager
Los Angeles City Fire Department
anna.olekszyk@lacity.org

Captain Dan Dragotto Los Angeles City Fire Department daniel.dragotto@lacity.org

Mr. Aaron Mungaray
Fire Inspector I
Los Angeles City Fire Department
aaron.mungaray@lacity.org

Mr. Sean Sullivan
General Services Department
City of Los Angeles
sean.sullivan@lacity.org